



FIG. 1B








FIG.3






FIG.4




FIG.5A





FIG.5B



DOPHER EN LOYDO

FIG.6A






FIG.6B



COMPLETE SERVICE

DOLETER HOLES




U.S. Patent

Nov. 3, 1998

Sheet 7 of 8

5,831,758





Nov. 3, 1998

Sheet 8 of 8

5,831,758

carcara a a a a a a a a

FIG.9

